



Bechtel Communications



Safety Bulletin

January 22, 2008

Defective Hooks

Elk River Safety Equipment is reporting a possible defect in hook 13217, as pictured below. The defect is associated with being able to open by applying pressure on either side (the hook "pops open"). On the gate of the hook, it will say "Gate strength 3600lbs."



13217

Please inspect equipment ASAP and if 13217 is identified, **immediately take it out of service** and notify your supervisor.

ES&H COMMUNICATION MEETING

Project _____ **Market/City/Site** _____

Topic: _____

Contractor/Subcontractor _____

Conducted by: _____

Date: _____

Please sign in below:

Employee

ID #

| | |
|-------|-------|
| _____ | _____ |
| _____ | _____ |
| _____ | _____ |
| _____ | _____ |
| _____ | _____ |
| _____ | _____ |
| _____ | _____ |
| _____ | _____ |
| _____ | _____ |
| _____ | _____ |

Comments/Suggestions

Supervisor's signature _____

Retain Completed Attendance Form in Market Office files